

Environmental Information Regulations – Response - 26831

1. *Please can you send me details of the number of times the Council or their approved contractors have undertaken repairs on a faulty drain cover, (involving traffic lights). directly outside Wayside, Bury Road, BSE, IP30 0BS. On the A134.*

Please see below list of orders raised to repair a damaged gully or to repair the surrounding road surface as attached as per file named "26831-Report.pdf".

2. *I would also like to know the cost (per visit) for each time this faulty drain cover has been repaired, Including the actual cost plus the traffic light costs*

Prior to 01/10/2023 individual defect repair costs were not recorded. Those costs associated since are as per file named "26831-Report.pdf".

I need the information going back 5 years please.

Date Originated	L.A.Code	Defect Description	Location	Address 1	Address 2	Description	Priority Desc.	Unit Type	Approved Cost
30/10/2025	354788	Ironwork - Unlikely sunken/risen 25-99mm	North bound carriageway just before White painted House.	BURY ROAD	SICKLESMERE		2 Working Days	GULLY	422.95
29/08/2025	350706	Ironwork - Likely missing <299x199	near Cottage	BURY ROAD	SICKLESMERE	Emergency passed over from Network assurance Gully broken on A road HRA patch required around gully cover due to continuing failure.	2 Hours	CARRIAGEWAY	47.13
25/03/2025	337869	Cway Defects - Likely 40-100mm	Wayside	BURY ROAD	SICKLESMERE		10 Working Days	CARRIAGEWAY	66.99
27/06/2023	274199	Potholes - Likely 40-100mm	Wayside	BURY ROAD	SICKLESMERE	Defect size (include length, width) - 0.3m x 0.3m repair with viafix as permanent to allow flexibility as gully cover is safe, please using overbanding tape Depth of defect (mm) – Estimated at least	10 Working Days	CARRIAGEWAY	0
21/04/2022	248998	Potholes - Likely 40-100mm	Wayside House	BURY ROAD	SICKLESMERE	Repair size (include length, width & depth) - 1.0m x 1.0m, follow up order as discussed with Andy Moore Defect size (include length, width) - 1.0m x 0.2m Depth of defect (mm) – Not safe enough to	14 Calendar Weeks	CARRIAGEWAY	0
31/03/2022	247736	Flooding - Blocked/silted gully	Wayside House	BURY ROAD	SICKLESMERE	Description/cause of flooding - Gully is constantly blocked and surface is failing, if possible please jet and clean prior to patching works Extent (area and depth) - Position of flooding within h	5 Working Days	GULLY	0
31/03/2022	247735	Potholes - Likely 40-100mm	Wayside House	BURY ROAD	SICKLESMERE	Repair size (include length, width & depth) - 1.0m x 1.0m Defect size (include length, width) - 1.0m x 0.2m Depth of defect (mm) – Not safe enough to measure Position within highway - Channel M	10 Working Days	CARRIAGEWAY	0