


Environmental Information Regulations – Response - 26970

Defect reference number 48087

Please can you confirm:

1. the date of the most recent safety inspection for Lower Road, between Leather bottle Hill and Sommersham where this reported defect is located

See below screen shot of inspection system



Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type	CSI	Carriageway Safety Inspections	Survey	200573
Address	LEATHER BOTTLE HILL	LITTLE BLAKENHAM		
Date Due	24/12/2025			
Frequency	3 Months	Standard Frequency	No Frequency	
Time Required	0.10	Standard Time	1057.25	

Done Date/Time: 24/12/2025 00:31 (Blank = Now) Mark Activity as Complete?

Inspector: [REDACTED]

Next Due Date: 24/03/2026 (Blank = Calculated)

Defect found?: No

Description: [Empty text area]

Last updated by BRINP1 at 00:33 on 24/12/2025 Hand-held

Screenshot saved LIVE 13/03/26

2. the road's official category under your Highway Maintenance Operational Plan (HMOP).

This road is classed as a Type 3b.

