

Environmental Information Regulations – Response - 27336

The following issue 64104 has been getting worse over the last month and in my opinion these holes will cause an accident.

Please can you send me your risk assessment under the freedom of information

Hopefully, Highways can action works immediately?

All assessments of defects, including potholes, in completed in line with Suffolk County Councils Highways Maintenance Operational Plan. (HMOP) this can be found at <https://www.suffolk.gov.uk/asset-library/v2.2-hmop-2021-final-live-october-2023-updated-2.242.pdf>

Risk assessments are not formally recorded. What has been supplied is details of the inspection of the defect referred to in case 64104 that resulted in a repair order being commissioned has been supplied as a .pdf file named '27336_Report'.

Reactive Highways Maintenance - Matrix C - Carriageway Defects

Action Number:	141601
Action Type:	Reactive Highways Maintenance
Asset Type:	Carriageway
Asset:	Park Road, Stoke By Nayland, Suffolk
Defect Type:	Matrix C - Carriageway Defects
Due Date:	27/05/2026 07:41
Ordered Date:	22/05/2026 09:08
State:	Ordered
Location:	On blind left hand bend heading from Thrornington to Stoke by Nayland

Description:	Urgent - Deep potholes in line with wheel tracks on narrow road. No option to hit holes or divert into oncoming traffic.
Order Number:	13729
Priority:	P3 - 5 Working Days
Client Target Completion Due:	5 Day(s)
Contractor Target Completion Due:	5 Day(s)
Client Completion Due:	27/05/2026 07:41
Contractor Completion Due:	01/06/2026 16:30
Grid Ref.:	599969 235597
Likelihood:	Likely- 40-100mm
Defect length & width (specify mm or m):	0.8x1m
Defect depth / level difference (mm):	80mm
Action required:	Patch
Position in road/footway/verge:	edge
Speed limit (mph):	National
Road width (m):	5.8m
Footway width (m):	na
Available width for TM (m):	4m
Marked up on site?:	Yes
Volume of traffic/pedestrian movement:	Medium
Additional hazards:	bends
HAO Area:	HAO - All Areas Merged, HAO - Rougham 07
HAE Area:	HAE - Rougham
M Group Area:	MOA - Central

Attachments

20260522_090725.jpg:



3540.jpg:



3541.jpg:



3542.jpg:



3545.jpg:

