

Environmental Information Regulations – Response - 27118

Re: Maltward Avenue in Bury St Edmunds

My request relates to the above trees which I consider to be a danger to pedestrians and other road users due to dead boughs and branches either detached and hanging in the canopy or in danger of detaching and falling.

This matter was reported to Suffolk Highways in June 2025 and they declined to act. A complaint was raised and, after a course of emails, was finally addressed after boughs that I had indicated were in a dangerous state detached in heavy rain and light winds and fell to the pathway. As a result of this the final email from Jon Cracknell of Suffolk Highways, dated the 9th September 2025, stated that the matter had been passed to West Suffolk District Council for them to carry out a tree inspection.

An FOI to west Suffolk district council has confirmed that they received notification from Suffolk Highways regarding this matter on the 21/08/2025 and after investigation a report was returned to yourselves on the 28/11/2025.

My request is for the following information.

1. I would like to see a copy of the report as the trees are still in a dangerous condition and shedding branches and boughs onto the footpath and highway.

This will assist me in any future actions as, at this point in time, nothing has been done to address the state of the trees which still pose a danger to pedestrians and road users.

See attached report named: '27118 Maltward Avenue.PDF'

Redacted Information

All information released in response to a Freedom of Information Act 2000 (FOIA) or Environmental Information Regulation 2004 (EIR) request is deemed to be in the public domain. As such we must consider whether or not the requested information qualifies as personal information and should therefore not be released into the public domain.

The council has determined that this is personal information and is therefore exempt from disclosure under **section 40** of the FOIA and **regulation 13** of the EIR.

The Council considered the following, including the possible consequences of disclosure for the data subjects concerned and their reasonable expectations as to the use of their data:

- expectations of the individuals concerned about personal information being put into the public domain;
- reasonable expectations - the data subjects concerned would have a legitimate expectation of privacy concerning their personal information and would not have anticipated this being put into the public domain;
- whether or not the requested information could be anonymised; and
- balancing the individual's rights and the legitimate interests - In past cases the Information Commissioner has weighed the individual's rights to privacy against

the public interest in disclosure. There is no presumption in favour of releasing personal data.

This is an absolute exemption, which means that if the condition is satisfied there is no additional public interest test to consider.

In assessing fairness, the Council considered the likely consequences of disclosure of the requested information. Personal information should not be used in ways that have unjustified adverse effects on the individuals concerned. The council also considered whether such disclosure would be within the reasonable expectations of the individuals, given that any response to a request under the FOIA or EIR is deemed to be in the public domain. The council believes that in this instance it is not fair to disclose personal data and is therefore withholding the requested information under section 40 of the FOIA and regulation 13 of the EIR.



KaarbonTech



Suffolk County Council


Detailed Report

Prepared by:	Suffolk County Council
Address:	Endeavour House, 8 Russell Rd, Ipswich, Suffolk, IP1 2BX
Inspector's Name:	<input type="text" value="REDACTED"/>
Date of Report:	10-04-2026

Summary:


This tree and woodland survey was undertaken by a qualified inspector from ground level. It is advised that following any extreme weather conditions any damaged tree or tree movement that has occurred and noticed by persons on site or ground staff is reported to the surveyor for further advice or a revisit if required.

Overview Map




Maps: © Crown Copyright [and database rights] 2026 OS 10005243

Detailed Map 1



Maps: © Crown Copyright [and database rights] 2026 OS 10005243

Detailed Map 2



Maps: © Crown Copyright [and database rights] 2026 OS 100055243

Tree Info

Label on map	Species	Height (m)	Age Class	Next Inspection	Est. Duration
1	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013622 ; ROAD MALTWARD AVENUE ; CENTRE (583352, 263828); ROAD MALTWARD AVENUE ; CENTRE (583352, 263828); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Se Deadwood: Major - 1 Tree clear highway; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
2	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013625 ; ROAD MALTWARD AVENUE ; CENTRE (583319, 263847); ROAD MALTWARD AVENUE ; CENTRE (583319, 263847); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS clear highway crown ligting/raising to 3m; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
3	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013620 ; ROAD MALTWARD AVENUE ; CENTRE (583309, 263865); ROAD MALTWARD AVENUE ; CENTRE (583309, 263865); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground Level 1 Tree; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
4	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013586 ; ROAD MALTWARD AVENUE ; CENTRE (583186, 263993); ROAD MALTWARD AVENUE ; CENTRE (583186, 263993); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crown lifting/raising to 3m clear highway; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
5	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013585 ; ROAD MALTWARD AVENUE ; CENTRE (583212, 263941); ROAD MALTWARD AVENUE ; CENTRE (583212, 263941); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
6	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013626 ; ROAD MALTWARD AVENUE ; CENTRE (583243, 263912); ROAD MALTWARD AVENUE ; CENTRE (583243, 263912); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crown lifting/raising to 3m clear highway; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
7	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013618 ; ROAD MALTWARD AVENUE ; CENTRE (583168, 264003); ROAD MALTWARD AVENUE ; CENTRE (583168, 264003); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m ; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
8	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013589 ; ROAD MALTWARD AVENUE ; CENTRE (583121, 264059); ROAD MALTWARD AVENUE ; CENTRE (583121, 264059); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS clear highway crown lifting/raising to 3m; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
9	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013623 ; ROAD MALTWARD AVENUE ; CENTRE (583367, 263832); ROAD MALTWARD AVENUE ; CENTRE (583367, 263832); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crown lifting/raising to 3m clear highway; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
10	Sorbus (Sorbus species)			Ad hoc	0

Label on map	Species	Height (m)	Age Class	Next Inspection	Est. Duration
	KT ASSET ID 900013629; ROAD MALTWARD AVENUE ; CENTRE (583241, 263923); ROAD MALTWARD AVENUE ; CENTRE (583241, 263923); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
11	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013588; ROAD MALTWARD AVENUE ; CENTRE (583143, 264047); ROAD MALTWARD AVENUE ; CENTRE (583143, 264047); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
12	Betula pendula (Silver Birch)			Ad hoc	0
	KT ASSET ID 900013628; ROAD MALTWARD AVENUE ; CENTRE (583268, 263890); ROAD MALTWARD AVENUE ; CENTRE (583268, 263890); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
13	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013587; ROAD MALTWARD AVENUE ; CENTRE (583191, 263986); ROAD MALTWARD AVENUE ; CENTRE (583191, 263986); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
14	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013627; ROAD MALTWARD AVENUE ; CENTRE (583206, 263963); ROAD MALTWARD AVENUE ; CENTRE (583206, 263963); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
15	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013636; ROAD MALTWARD AVENUE ; CENTRE (583158, 264017); ROAD MALTWARD AVENUE ; CENTRE (583158, 264017); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS SE Fell Tree: Ground level - 1 tree ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
16	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013590; ROAD MALTWARD AVENUE ; CENTRE (583122, 264070); ROAD MALTWARD AVENUE ; CENTRE (583122, 264070); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS crown lifting/raising to 3m and clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
17	Sorbus aucuparia (Mountain-ash)			Ad hoc	0
	KT ASSET ID 900013621; ROAD MALTWARD AVENUE ; CENTRE (583295, 263877); ROAD MALTWARD AVENUE ; CENTRE (583295, 263877); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
18	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013630; ROAD MALTWARD AVENUE ; CENTRE (583118, 264082); ROAD MALTWARD AVENUE ; CENTRE (583118, 264082); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS crown lifting/raising to 3m clear highway ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
19	Sorbus (Sorbus species)			Ad hoc	0
	KT ASSET ID 900013624; ROAD MALTWARD AVENUE ; CENTRE (583333, 263836); ROAD MALTWARD AVENUE ; CENTRE (583333, 263836); INSPECTED AT 28 November 2025 12:00; INSPECTED BY ██████████; STEM DIAMETERS; COMMENTS SE Fell Tree: Ground level - 1 tree ; RPA 0m ² ; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;		NO WORKS REQUIRED AT THE TIME OF INSPECTION		
20	Sorbus aucuparia (Mountain-ash)			Ad hoc	0

Label on map	Species	Height (m)	Age Class	Next Inspection	Est. Duration	
	KT ASSET ID 900013619 ; ROAD MALTWARD AVENUE ; CENTRE (583284, 263888); ROAD MALTWARD AVENUE ; CENTRE (583284, 263888); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground Level - 1 Tree; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;				NO WORKS REQUIRED AT THE TIME OF INSPECTION	

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583352, 263828)

Asset Details

External ID	
KTS Unique ID	900013622


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
1	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013622 ; ROAD MALTWARD AVENUE ; CENTRE (583352, 263828); ROAD MALTWARD AVENUE ; CENTRE (583352, 263828); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS Se Deadwood: Major - 1 Tree clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583319, 263847)

Asset Details

External ID	
KTS Unique ID	900013625


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
2	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013625 ; ROAD MALTWARD AVENUE ; CENTRE (583319, 263847); ROAD MALTWARD AVENUE ; CENTRE (583319, 263847); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS clear highway crown lighting/raising to 3m ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583309, 263865)

Asset Details

External ID	
KTS Unique ID	900013620


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
3	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013620 ; ROAD MALTWARD AVENUE ; CENTRE (583309, 263865); ROAD MALTWARD AVENUE ; CENTRE (583309, 263865); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground Level 1 Tree ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583186, 263993)

Asset Details

External ID	
KTS Unique ID	900013586


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
4	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013586 ; ROAD MALTWARD AVENUE ; CENTRE (583186, 263993); ROAD MALTWARD AVENUE ; CENTRE (583186, 263993); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583212, 263941)

Asset Details

External ID	
KTS Unique ID	900013585


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
5	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013585 ; ROAD MALTWARD AVENUE ; CENTRE (583212, 263941); ROAD MALTWARD AVENUE ; CENTRE (583212, 263941); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway; RPA 0m²; RPA RADIUS 0.0m; SUGGESTED TRAFFIC MANAGEMENT None; INSPECTION TYPE Cyclical;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583243, 263912)

Asset Details

External ID	
KTS Unique ID	900013626


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
6	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013626 ; ROAD MALTWARD AVENUE ; CENTRE (583243, 263912); ROAD MALTWARD AVENUE ; CENTRE (583243, 263912); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583168, 264003)

Asset Details

External ID	
KTS Unique ID	900013618


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
7	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013618 ; ROAD MALTWARD AVENUE ; CENTRE (583168, 264003); ROAD MALTWARD AVENUE ; CENTRE (583168, 264003); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583121, 264059)

Asset Details

External ID	
KTS Unique ID	900013589


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
8	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013589 ; ROAD MALTWARD AVENUE ; CENTRE (583121, 264059); ROAD MALTWARD AVENUE ; CENTRE (583121, 264059); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS clear highway crown lifting/raising to 3m; RPA 0m²; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583367, 263832)

Asset Details

External ID	
KTS Unique ID	900013623


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
9	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013623 ; ROAD MALTWARD AVENUE ; CENTRE (583367, 263832); ROAD MALTWARD AVENUE ; CENTRE (583367, 263832); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583241, 263923)

Asset Details

External ID	
KTS Unique ID	900013629


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
10	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013629 ; ROAD MALTWARD AVENUE ; CENTRE (583241, 263923); ROAD MALTWARD AVENUE ; CENTRE (583241, 263923); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583143, 264047)

Asset Details

External ID	
KTS Unique ID	900013588


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
11	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013588 ; ROAD MALTWARD AVENUE ; CENTRE (583143, 264047); ROAD MALTWARD AVENUE ; CENTRE (583143, 264047); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583268, 263890)

Asset Details

External ID	
KTS Unique ID	900013628


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
12	Betula pendula (Silver Birch)				N/A
KT ASSET ID 900013628 ; ROAD MALTWARD AVENUE ; CENTRE (583268, 263890); ROAD MALTWARD AVENUE ; CENTRE (583268, 263890); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583191, 263986)

Asset Details

External ID	
KTS Unique ID	900013587


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
13	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013587 ; ROAD MALTWARD AVENUE ; CENTRE (583191, 263986); ROAD MALTWARD AVENUE ; CENTRE (583191, 263986); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583206, 263963)

Asset Details

External ID	
KTS Unique ID	900013627


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
14	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013627 ; ROAD MALTWARD AVENUE ; CENTRE (583206, 263963); ROAD MALTWARD AVENUE ; CENTRE (583206, 263963); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583158, 264017)

Asset Details

External ID	
KTS Unique ID	900013636


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
15	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013636 ; ROAD MALTWARD AVENUE ; CENTRE (583158, 264017); ROAD MALTWARD AVENUE ; CENTRE (583158, 264017); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground level - 1 tree ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583122, 264070)

Asset Details

External ID	
KTS Unique ID	900013590

Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
16	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013590 ; ROAD MALTWARD AVENUE ; CENTRE (583122, 264070); ROAD MALTWARD AVENUE ; CENTRE (583122, 264070); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m and clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583295, 263877)

Asset Details

External ID	
KTS Unique ID	900013621


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
17	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013621 ; ROAD MALTWARD AVENUE ; CENTRE (583295, 263877); ROAD MALTWARD AVENUE ; CENTRE (583295, 263877); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS Crown lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583118, 264082)

Asset Details

External ID	
KTS Unique ID	900013630


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
18	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013630 ; ROAD MALTWARD AVENUE ; CENTRE (583118, 264082); ROAD MALTWARD AVENUE ; CENTRE (583118, 264082); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED] ; STEM DIAMETERS ; COMMENTS crow lifting/raising to 3m clear highway ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583333, 263836)

Asset Details

External ID	
KTS Unique ID	900013624


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
19	Sorbus (Sorbus species)				N/A
KT ASSET ID 900013624 ; ROAD MALTWARD AVENUE ; CENTRE (583333, 263836); ROAD MALTWARD AVENUE ; CENTRE (583333, 263836); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground level - 1 tree ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		

Location Details

Road	MALTWARD AVENUE
Parish or ward	Minden
what3words	
Easting/northing	(583284, 263888)

Asset Details

External ID	
KTS Unique ID	900013619


Asset History Summary

28 November 2025 12:00	Tree Inspection	Cyclical
------------------------	-----------------	----------

Current Work Items

No current work items

Map of asset location:



Inspection: 28 Nov 2025 12:00:00 [REDACTED]

No	Species	Height (m)	Age Class	Next Inspection	Est. Duration
20	Sorbus aucuparia (Mountain-ash)				N/A
KT ASSET ID 900013619 ; ROAD MALTWARD AVENUE ; CENTRE (583284, 263888); ROAD MALTWARD AVENUE ; CENTRE (583284, 263888); INSPECTED AT 28 November 2025 12:00 ; INSPECTED BY [REDACTED]; STEM DIAMETERS ; COMMENTS SE Fell Tree: Ground Level - 1 Tree ; RPA 0m² ; RPA RADIUS 0.0m ; SUGGESTED TRAFFIC MANAGEMENT None ; INSPECTION TYPE Cyclical ;			NO WORKS REQUIRED AT THE TIME OF INSPECTION		