

Environmental Information Regulations – Response - 27653

Cr 70005 Formal Notice regarding mobile home located in layby to the east of the moorings, ipswich road ip7 6be

I am writing to formally address the current situation regarding my residency in my motor home at [Location of Layby].

Firstly, I wish to highlight that the condition of this layby clearly indicates a total lack of maintenance for several years. The degradation of the road surface, coupled with the significant accumulation of litter, suggests that public funds have not been effectively utilized here for some time.

Pursuant to the Freedom of Information Act 2000, I hereby submit a formal request for all records detailing maintenance costs, works commissioned, and funds expended by the local authority on this specific layby over the past ten years.

Please see what3words to indicate location [///brothers.combos.splashes](https://www.what3words.com/splashes-brothers-combos)

NB Regarding accumulation of litter, this issue should be addressed to District/Borough Council who have responsibility for such matters.

If you have not already done so, then you may wish to write to the Borough and District Councils of Suffolk:

- Babergh Mid Suffolk District Council
[Freedom of Information - Babergh District Council - babergh.gov.uk / midsuffolk.gov.uk](https://www.babergh.gov.uk/)
- East Suffolk
[FOI and EIR making a request | East Suffolk Council](https://www.eastsuffolk.gov.uk/foi)
- West Suffolk
[Freedom of information](https://www.westsuffolk.gov.uk/foi)
- Ipswich Borough Council
[Freedom Of Information \(FOI\) | ipswich.gov.uk](https://www.ipswich.gov.uk/foi)

Suffolk County Council does not hold specific records relating to this lay-by. The information provided consists of a list of all maintenance activities carried out on Ipswich Road, Hadleigh. The relevant location can be identified using the descriptions and Ordnance Survey grid references included within the records.

Please note that, prior to October 2023, the cost of individual defect repairs was not recorded separately. As a result, specific repair costs for defects during this period cannot be provided.

Details as per attached file named '27653_Report.pdf'.

Redacted Information

All information released in response to a Freedom of Information Act 2000 (FOIA) or Environmental Information Regulation 2004 (EIR) request is deemed to be in the public domain. As such we must consider whether or not the requested information qualifies as personal information and should therefore not be released into the public domain.

The council has determined that this is personal information and is therefore exempt from disclosure under **section 40** of the FOIA and **regulation 13** of the EIR.

The Council considered the following, including the possible consequences of disclosure for the data subjects concerned and their reasonable expectations as to the use of their data:

- expectations of the individuals concerned about personal information being put into the public domain;
- reasonable expectations - the data subjects concerned would have a legitimate expectation of privacy concerning their personal information and would not have anticipated this being put into the public domain;
- whether or not the requested information could be anonymised; and
- balancing the individual's rights and the legitimate interests - In past cases the Information Commissioner has weighed the individual's rights to privacy against the public interest in disclosure. There is no presumption in favour of releasing personal data.

This is an absolute exemption, which means that if the condition is satisfied there is no additional public interest test to consider.

In assessing fairness, the Council considered the likely consequences of disclosure of the requested information. Personal information should not be used in ways that have unjustified adverse effects on the individuals concerned. The council also considered whether such disclosure would be within the reasonable expectations of the individuals, given that any response to a request under the FOIA or EIR is deemed to be in the public domain. The council believes that in this instance it is not fair to disclose personal data and is therefore withholding the requested information under section 40 of the FOIA and regulation 13 of the EIR.

Date Originated	LA Code	Detect Description	Location	Grid Reference Easting	Grid Reference Northing	Address 1	Address 2	Description	Priority Code & Desc.	Priority Det	Planned Start Date	Comp Due Date	Date Completed	Action Type Description	Stage Desc.	Defect	Action	Unit Type	Latest Cost	NSG Ref	Unit No.	Approved Cost	
09/12/2025	357776	Road Sign - Very likely/Likely mandatory	On roundabout junction with Lady Lane and Ellen Aldous avenue	603769.66	243527.53	IPSWICH ROAD	HADLEIGH		520 Working Days	20 Working	23/12/2025	12/01/2026	23/12/2025	Default Action	APPROVED	RG1B	DEF	CARRIAGE	1,390.21	15/11/148		1,390.21	
01/12/2025	357027	Emergency Response	A1071 Ipswich Road, IP7 6BG	605566.68	243703.67	IPSWICH ROAD	HADLEIGH	A1071 Ipswich Road, IP7 6BG - RSPB Wolves Wood - reporter advised of a tree down blocking the road.	12 Hours	2 Hours		02/12/2025	02/12/2025	Default Action	APPROVED	R21B	DEF	CARRIAGE	23.27	15/11/148		23.27	
11/11/2025	355423	Emergency Response	on the roundabout connecting B1070 and the A1071	605378.62	243529	IPSWICH ROAD	HADLEIGH	motorbike has lost traction and crashed there is a 30 metre spill around this roundabout and with vehicles passing over it is spreading this further.	12 Hours	2 Hours		11/11/2025	11/11/2025	Default Action	APPROVED	R21B	DEF	CARRIAGE	34.97	15/11/148		34.97	
23/07/2025	348264	Emergency Response	Near Claremont Cottage, IP8 3PA	605930.07	243786.16	IPSWICH ROAD	HADLEIGH	Daiged drain cover on the carriageway. /fitter, slider, spacesspit	12 Hours	2 Hours		23/07/2025	23/07/2025	Default Action	APPROVED	R21B	DEF	CARRIAGE	23.27	15/11/148		23.27	
24/06/2025	346196	Ironwork - Very likely missing >300x200	~250m East of access to Beestons	605600.08	243687.97	IPSWICH ROAD	HADLEIGH	Follow-up to 340346	520 Working Days	20 Working	21/07/2025	23/07/2025	21/07/2025	Default Action	APPROVED	R01B	DEF	CARRIAGE	572.8	15/11/148		572.8	
28/05/2025	343659	Surface Dressing	Surfacing joint west of Wolves Wood to joint east of Wolves viewlnroad	604741.28	243470.32	IPSWICH ROAD	HADLEIGH	Construction Order - Ipswich Road Hadleigh - Surface Dressing 25/26 Scheme No. 229235 Rogue 1 - Supply and fix Allux Studs White/White - 234 No. (Amended by client to SOR item: 1200-04-001).	8 Planned Works	Planned Wk	28/07/2025	28/07/2025	31/08/2025	Construction/Works	APPROVED	F13B	P07	CARRIAGE	51,808.95	15/11/148		51,808.95	
22/04/2025	340346	Emergency Response	Nr Ladyby gully ref 60119104	605600.08	243687.97	IPSWICH ROAD	HADLEIGH	Emergency order raised from email from Flowline (attached) All measures estimated or from Insight	12 Hours	2 Hours	22/04/2025	22/04/2025	22/04/2025	Default Action	APPROVED	R21B	DEF	GULLY	32.53	15/11/148		32.53	
01/04/2025	338821	Emergency Response	jw B1070 Gallowes Hill, IP7 6UJ	600222.36	245525.12	IPSWICH ROAD	HADLEIGH	RTIC - directional sign has been struck and damaged. CAD30. //riper, conqueror, sharpen	12 Hours	2 Hours	01/04/2025	01/04/2025	01/04/2025	Default Action	APPROVED	R21B	DEF	CARRIAGE	17.49	15/11/148		17.49	
25/03/2025	337750	Sd Prep (In Year)	Surfacing joint west of Wolves Wood to joint east of Wolves viewlnroad	604741.28	243470.32	IPSWICH ROAD	HADLEIGH	Diaged drain cover on the carriageway. /fitter, slider, spacesspit	8 Planned Works	Planned Wk	06/05/2025	13/05/2025	14/05/2025	Construction/Works	APPROVED	F12B	P07	CARRIAGE	84,955.16	15/11/148		84,955.16	
17/03/2025	336955	Road Signs	Approx. 170m Southeast of Redhill Road	603535.78	243684.82	IPSWICH ROAD	HADLEIGH	Scheme Set-up - Ipswich Road, Hadleigh Vegetation cut back. Vegetation to be cut back fro 2no. signs at 2no. sites.	9 Minor Planned Works	Minor Plan	01/04/2025	31/03/2026	05/11/2025	Scheme Set-up	COMPLETED	F33B	P11	SIGN	0	15/11/148		0	
23/01/2025	331050	Road Sign - Possible warning sign	Just passed Ladyby	603863.51	243509.28	IPSWICH ROAD	HADLEIGH	Follow-up to LA 331041	520 Working Days	20 Working	03/02/2025	20/02/2025	03/02/2025	Default Action	APPROVED	RG2B	DEF	SIGN	247.4	15/11/148		247.4	
23/01/2025	331041	Emergency Response	Near the Starbucks IP7 6SF	603911.18	243516.97	IPSWICH ROAD	HADLEIGH	100 mile marker sign has been hit by a car and is down on the ground. CAD6 23101	12 Hours	2 Hours	23/01/2025	23/01/2025	23/01/2025	Default Action	APPROVED	R21B	DEF	CARRIAGE	67.45	15/11/148		67.45	
19/11/2024	325722	Road Signs	Approx. 170m Southeast of Redhill Road	603535.78	243684.82	IPSWICH ROAD	HADLEIGH	Construction Order - Ipswich Road, Hadleigh Vegetation cut back. Scheme No. 265430	9 Minor Planned Works	Minor Plan	01/04/2025	31/03/2026	01/04/2025	Construction/Works	APPROVED	F33B	P07	SIGN	629.5	15/11/148		629.5	
27/08/2024	321767	Road Signs	Approx. 170m Southeast of Redhill Road	603535.78	243684.82	IPSWICH ROAD	HADLEIGH	Construction Estimate - Ipswich Road, Hadleigh Vegetation cut back. Please provide a Construction Cost Estimate for the required works.	8 Planned Works	Planned Wk	27/09/2024	03/01/2025	05/11/2025	Cost Estimate	COMPLETED	F33B	P09	SIGN	0	15/11/148		0	
27/09/2024	321766	Road Signs	Approx. 170m Southeast of Redhill Road	603535.78	243684.82	IPSWICH ROAD	HADLEIGH	TM Assessment - Ipswich Road, Hadleigh Vegetation cut back. Please provide a TM Assessment for the required works.	9 Minor Planned Works	Minor Plan	27/09/2024	03/01/2025	01/10/2024	TM Assessment	APPROVED	F33B	P12	SIGN	12.49	15/11/148		12.49	
27/09/2024	321764	Road Signs	Approx. 170m Southeast of Redhill Road	603535.78	243684.82	IPSWICH ROAD	HADLEIGH	Scheme Set-up - Ipswich Road, Hadleigh Vegetation cut back. Vegetation to be cut back fro 2no. signs at 2no. sites.	9 Minor Planned Works	Minor Plan	27/09/2024	03/01/2025	05/11/2025	Scheme Set-up	APPROVED	F33B	P11	SIGN	0	15/11/148		0	
13/05/2024	308268	Sd Prep (In Year)	Surfacing joint west of Wolves Wood to joint east of Wolves viewlnroad	604741.28	243470.32	IPSWICH ROAD	HADLEIGH	Scheme Set-up - Ipswich Road Hadleigh - Surface Dressing Prep 25/26 Please design the preparation work (SDP) and surface dressing (SD) aspects of this scheme and feedback fully formed design p	8 Planned Works	Planned Wk	01/04/2025	31/03/2026		Scheme Set-up	APPROVED	F12B	P11	CARRIAGE	0	15/11/148		0	
08/04/2024	304034	Coway Defects - Likely 40-100mm	In layby - 100m East of access track to Wolves Farm	604789.62	243479.73	IPSWICH ROAD	HADLEIGH	Cat 6 to cat 5 due to two other cat 5 defects here	520 Working Days	20 Working	13/05/2024	08/05/2024	13/05/2024	Default Action	APPROVED	RG2B	DEF	CARRIAGE	68.72	15/11/148		68.72	
08/04/2024	304032	Coway Defects - Very likely >100mm	In layby - 100m East of access track to Wolves Farm	604789.62	243479.73	IPSWICH ROAD	HADLEIGH		520 Working Days	20 Working	08/05/2024	08/05/2024	08/05/2024	Default Action	APPROVED	RG1B	DEF	CARRIAGE	163.36	15/11/148		163.36	
08/04/2024	304032	Coway Defects - Very likely >100mm	In layby - 100m East of access track to Wolves Farm	604789.62	243479.73	IPSWICH ROAD	HADLEIGH		520 Working Days	20 Working	08/05/2024	08/05/2024	08/05/2024	Default Action	APPROVED	RG1B	DEF	CARRIAGE	188.21	15/11/148		188.21	
02/11/2023	283973	Emergency Response	Near to Beeston Coach Station - IP7 6BG	604448.74	243493.35	IPSWICH ROAD	HADLEIGH	Reporter advised of a tree down blocking the road. Called through to IBC from [REDACTED] (OOH operative)	12 Hours	2 Hours	02/11/2023	02/11/2023	02/11/2023	Default Action	APPROVED	R21B	DEF	CARRIAGE	21.11	15/11/148		21.11	
04/10/2023	280902	Surface Dressing	Surfacing joint west of Wolves Wood to joint east of Wolves viewlnroad	604741.28	243470.32	IPSWICH ROAD	HADLEIGH	Scheme Set Up - Ipswich Road Hadleigh - Surface Dressing 25/26 Please design the preparation work (SDP) and surface dressing (SD) aspects of this scheme and feedback fully formed design packs includ	8 Planned Works	Planned Wk	01/04/2025	31/03/2026		Scheme Set-up	APPROVED	F13B	P11	CARRIAGE	0	15/11/148		0	
02/10/2023	280436	Resurfacing	Surfacing joint west of Wolves Wood to joint east of Wolves viewlnroad	604741.28	243470.32	IPSWICH ROAD	HADLEIGH	Scheme Set Up - Ipswich Road Hadleigh - Surface Dressing 24/25 Please design the preparation work (SDP) and surface dressing (SD) aspects of this scheme and feedback fully formed design packs includ	8 Planned Works	Planned Wk	01/10/2023	31/08/2024		Scheme Set-up	CANCELLED	F10B	P11	CARRIAGE	0	15/11/148		0	
28/09/2023	280248	Road Sign - Possible warning sign	Roundabout junction with Lady Lane/Ellen Aldous Avenue	603774.28	243533.09	IPSWICH ROAD	HADLEIGH	Other within SLA - Priority as required to get within SLA. Re-raised prior order from previous contract. Original LA 27/09/2023 Cat changed meet original SLA. If it u	410 Working Days	10 Working	27/11/2023	16/10/2023	27/11/2023	Default Action	APPROVED	RG2B	DEF	CARRIAGE	569.16	15/11/148		569.16	
25/08/2023	277864	Sign - Possible	Roundabout junction with Lady Lane/Ellen Aldous Avenue	603774.8	243533.09	IPSWICH ROAD	HADLEIGH	Type of road sign/vidia, number and size - 2x Chevron dia 515 1350x600mm and 2 7m structural bar Type of damage/action required (replace, remove, reset, realign etc) - Bent out of shape, replace Post	8 Weeks	8 Weeks		25/08/2023	20/09/2023	Default Action	APPROVED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
15/08/2023	277109	Potholes - Likely 40-100mm	In layby at access to Cobbolds Farm	605142.47	243509.92	IPSWICH ROAD	HADLEIGH	Defect size (include length, width) - 1.2x0.9m, 1.6x1m, 1.5x1m, 1.6x0.6m, 0.6x0.6m, 2.4x0.6m Depth of defect (mm) - 80mm, rest 40-50mm Position within highway - Across layby Marked on s	8 Weeks	8 Weeks		15/08/2023	13/09/2023	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
15/08/2023	277108	Potholes - Likely 40-100mm	In layby before access to Celotex Depot coming from Ipswich	605529.77	243688.07	IPSWICH ROAD	HADLEIGH	Defect size (include length, width) - 4.8x1.1m Depth of defect (mm) - 130mm deepest Position within highway - Edge of carriageway/layby Marked on site (yes/no) - yes Road Type (2, 3a, 3b, 4a or	520 Working Days	20 Working Days		15/08/2023	25/08/2023	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
08/03/2023	265559	Potholes - Likely 40-100mm	10m East of access to Wolves Farm	604672.89	243485.72	IPSWICH ROAD	HADLEIGH	Defect size (include length, width) - 1.2x0.5m Depth of defect (mm) - 50mm (unable to measure due to traffic conditions) Position within highway - Wheel track/edge Marked on site (yes/no) - yes	410 Working Days	10 Working Days		24/03/2023	21/03/2023	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
13/01/2023	261611	Potholes - Likely 40-100mm	Between access to bus depot and layby by Cobbolds Farm	605249.38	243563.72	IPSWICH ROAD	HADLEIGH	Defect size (include length, width) - 1.8x0.8m Depth of defect (mm) - 40mm Position within highway - Edge/wheel track Marked on site (yes/no) - no, too much traffic Road Type (2, 3a, 3b, 4a or 4	410 Working Days	10 Working Days		30/01/2023	25/01/2023	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
19/05/2022	259617	Vegetation - Forcing traffic in opp lane	Outside Wolves View in layby	604290.78	243540.62	IPSWICH ROAD	HADLEIGH	Type of vegetation (to include the size of branch and trunk etc) - Tree fallen into layby, coming 3m into the road, looks about 5m long with lots of protruding branches. Decryption of Hazard (is the	35 Working Days	5 Working Days		27/05/2022	27/05/2022	Default Action	COMPLETED	RP4A	DEF	CARRIAGE	0	15/11/148		0	
16/12/2021	240885	Drainage Infrastructure	Gully ID's: 60119243, 60119244, 60119245, 60119230, 60119236 and more	604251	243506.26	IPSWICH ROAD	HADLEIGH	Zero value LA Claims will be paid on Combi/civilis blanket LA229956, Gully ID 60119243 has a broken cover with a 100% silt build up, at the co-ordinates above. Gully 60119244 has a broken cover with a	8 Planned Works	Planned Wk	16/12/2021		30/04/2022	30/04/2024	Default Action	COMPLETED	GM0B	DEF	DRAIN	0	15/11/148		0
09/09/2021	235789	Vegetation - Obscured visibility at junction	Edit of layby outside Wolves View	604339.39	243506.26	IPSWICH ROAD	HADLEIGH	Type of vegetation (to include the size of branch and trunk etc) - 30m of branches overhanging into carriageway and 10m of vegetation obscuring exit to junction. Decryption of Hazard (is the hazard o	614 Calendar Weeks	14 Calendar Weeks		17/12/2021	13/01/2021	Default Action	COMPLETED	RP5A	DEF	CARRIAGE	0	15/11/148		0	
07/12/2020	218065	Potholes - Likely 40-100mm	In second layby on the left heading towards Ipswich	604782.42	243467.32	IPSWICH ROAD	HADLEIGH	Description of defect - Patch of potholes and deterioration. Size of defect (area or diameter) - 206m at the widest Depth of defect (mm) - 50mm, higher in some places but can't get a picture. Positi	6 Months Covid-19	6 Months Covid-19		15/08/2021	15/08/2021	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
12/08/2020	211643	Potholes - Likely 40-100mm	In layby near to Cobbolds Farm	605123.05	243500.63	IPSWICH ROAD	HADLEIGH	Description of defect - 12x potholes. Size of defect (area or diameter) - 1x0.9m, 3.7x2.3m, 0.8x0.5m, 3.4x1.2m, 2.8x1.1m, 2x1m, 3.8x1.1m, 2.4x1m, 3.8x1.8m, 2.3x1.3m, 10x2.6m, 4.5x1.6m, Roughly 68 squa	6 Months Covid-19	6 Months Covid-19	08/12/2020	08/12/2020	17/02/2021	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
10/08/2020	211550	Potholes - Likely 40-100mm	In layby closest to layby at bus depot	604786.47	243533.09	IPSWICH ROAD	HADLEIGH	Type of vegetation (to include the size of branch and trunk etc) - Tree fallen into layby, coming 3m into the road, looks about 5m long with lots of protruding branches. Decryption of Hazard (is the	410 Working Days	10 Working Days		25/08/2020	12/09/2020	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
10/08/2020	211550	Potholes - Likely 40-100mm	Outside Tudorcroft in Layby	603967.1	243489.24	IPSWICH ROAD	HADLEIGH	Description of defect - Pothole x5 Size of defect (area or diameter) - 2x1.4m, 1x0.5m, 1.4x0.6m, 1.4x0.6m, 1.8x1.8m (not sprayed up as debris on the ground stops the paint sticking) Depth of defect	410 Working Days	10 Working	12/08/2020	12/08/2020	12/08/2020	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
07/05/2020	205918	Potholes - Likely 40-100mm	In layby nearby to Beestons	605759.44	243733.36	IPSWICH ROAD	HADLEIGH	Description of defect - Pothole. Size of defect (area or diameter) - 3.7x1m Depth of defect (mm) - 90mm Position within highway - On border between road and layby Marked on site (yes/no) - yes Roa	410 Working Days	10 Working	14/05/2020	14/05/2020	14/05/2020	Default Action	COMPLETED	RG2A	DEF	CARRIAGE	0	15/11/148		0	
09/07/2019	188241	Vegetation - Obscured visibility at junction	Roundabout inside the barriers	603777.08	243513.01	IPSWICH ROAD	HADLEIGH	Type of vegetation (to include the size of branch and trunk etc) - grass/weeds Decryption of Hazard (is the hazard overhanging or at ground level etc) - ground level Position within highway (verge,	520 Working Days	20 Working Days		07/08/2019	06/08/2019	Default Action	APPROVED	RP5	DEF	VERGE	0	15/11/148		0	
04/09/2018	173045	Improvement Schemes	Lady Lane RBT Approaches	604811.88	275869.59	IPSWICH ROAD	HADLEIGH	Cat 8 Professional Services Order funded by Development Management Design to de-restrict Lady Lane RBT Designer [REDACTED] Road Safety & Speed Management Technician)	8 Planned Works	Planned Wk	04/09/2018	01/01/2019	14/09/2018	Default Action	APPROVED	GM30	DEF	CARRIAGE	74.52	15/11/148		74.52	
21/06/2018	172554	Carriageway Signs	Both approaches to B1070 Lady Lane RBT	603751.17	243526.21	IPSWICH ROAD	HADLEIGH	Instal 2 x 750mm NSL terminal signs on existing lamp columns to de-restrict area around Lady Lane RBT as per plans. [REDACTED] Look no roadzone for further information. [REDACTED] 01473 265036.	8 Planned Works	Planned Wk	21/08/2018	30/11/2018	08/10/2018	Default Action	APPROVED	GM15	DEF	ROW SIGN	521.65	15/11/148		521.65	
14/06/2018	169254	Potholes - Very likely >100mm	Entrance to signed layby and along the length of the layby.	604788.44	243775.55	IPSWICH ROAD	HADLEIGH	Description of defect - 3x potholes. Size of defect (area or diameter) - ph1>0.72m2, ph2>2.04m2, ph3>0.54m2 Depth of defect (mm) - ph1->90mm, ph2->130mm, ph3->85mm Position within highway - in layby p	410 Working Days	10 Working Days		29/06/2018	26/06/2018	Default Action	APPROVED	RG1	DEF	CARRIAGE	0	15/11/148		0	
16/02/2017	143793	Debris - Very likely hazard	Opposite Beestons	605106.06	243525.88	IPSWICH ROAD	HADLEIGH	KMG ref: 74838 - RETROSPECTIVE ORDER. Oil patch on the road. Called in by [REDACTED] passed to [REDACTED] (PH OOH)	12 Hours	2 Hours		17/02/2017	16/02/2017	Default Action	APPROVED	RA1	DEF	CARRIAGE	0	15/11/148		0	
17/09/2016	137229	Debris - Very likely hazard	100yds south of roundabout with Lady Lane	603777.76	243451.52	IPSWICH ROAD	HADLEIGH	KMG Ref: 68706 Police CAD 201. Vehicle has broken down and left oil slick on road - 2Ht wide and several feet long	12 Hours	2 Hours		18/09/2016	17/09/2016	Default Action	APPROVED	RA1	DEF	CARRIAGE	0	15/11/148		0	
22/08/2016	136110	Pothole - Exceeding 600x600x50mm	As plotted	605729.58	243721.26	IPSWICH ROAD	HADLEIGH	Description - Please fill 2 x potholes. Marked on site. Dropped to cat4 as on layby. Road Type (2, 3															

Recorded	Reference	Address 1	Address 2	Location Text	Completed	Entity Type	Sub-Type	State	Spent-to-date
12/03/2026 15:00	68496	IPSWICH ROAD	HADLEIGH	Just east of layby outside Beestons	31/03/2026 23:14	Reactive Maintenance	Reactive Highways Maintenance	Approved	348.96
12/03/2026 14:26	68458	IPSWICH ROAD	HADLEIGH	On junction with layby opposite Wolves Farm Lane	31/03/2026 23:43	Reactive Maintenance	Reactive Highways Maintenance	Approved	127.07