### MARTELLO TOWER 'Z' **ALDERTON**

Grid Reference TM 361 419

List Grade II and Scheduled Ancient Monument

**Conservation Area** 

Description Martello Tower. Built c.1810-12 as part of defence line

against threat of invasion by Napoleon. Brick with ashlar

dressings. Three storeys. Teardrop shaped plan.

Suggested Use

С Risk Priority Condition Poor

Reason for Risk Outer brick skin is peeling away, leaving about 40% of inner

structure exposed.

First on Register

Owner/Agent Exors of D R Mann. Agent: P J Mann, High House,

Bawdsey, Woodbridge IP12 3AW

**Current Availability** 

Not for sale

Notes The owners are investigating potential users or uses for the

> building in order to facilitate essential repair/conservation works. The area around the tower is no longer in cultivation.

On the English Heritage Register of Buildings at Risk.

Robert Scrimgeour 01394 444616 Contact

1997



## CHAPEL, BAWDSEY MANOR BAWDSEY

Grid Reference TM 333 382

List Grade Curtilage building to Bawdsey Manor (II\*)

Conservation Area No

Description A pre-fabricated timber-framed building with corrugated

metal covering, consisting of a porch, nave and chancel.

Suggested Use

Risk Priority A

Condition Very bad

Reason for Risk Lack of general maintenance has led to decay of timber

frame and floor.

First on Register 2009

Owner/Agent Mr B Toettcher, Bawdsey Manor, Bawdsey, Woodbridge

**IP12 3AZ** 

Current Availability Not for sale

Notes The chapel was erected by Sir Cuthbert Quilter for use by

the Estate workers, c.1900 and is of considerable interest as

a privately commissioned and run chapel.



## LEMONARY 40M N OF BAWDSEY MANOR BAWDSEY

Grid Reference TM 337 379

List Grade II Conservation Area No

Description Timber-framed glasshouse used as a lemonary. Built c.1900

in classical design of symmetrical bays divided by fluted Roman Doric pilasters. Set within a large walled garden.

Risk Priority C

Condition Very bad

Reason for Risk Lack of maintenance has allowed decay to frame and metal

supports causing structural problems.

First on Register 1995

Owner/Agent Mr B Toettcher, Bawdsey Manor, Bawdsey, Woodbridge

IP12 3AZ

Current Availability Not for sale

Notes Described as an Orangery in the list description. In a

dilapidated condition when listed in 1988 and has deteriorated since. Some missing parts are in storage.



# RADAR RECEIVER BLOCK, BAWDSEY MANOR BAWDSEY

Grid Reference TM 336 380

List Grade II Conservation Area No

Description Concrete and brick radar block, 1937. Site of pioneering

radar development.

Suggested Use Museum / storage ancillary to house or land use.

Risk Priority C Condition Fair

Reason for Risk Metal reinforcement is rusting causing concrete to spall.

Lack of general maintenance, trees growing on earth bank.

First on Register 2000

Owner/Agent Mr B Toettcher, Bawdsey Manor, Bawdsey, Woobridge IP12

3AZ

Current Availability Not known

Notes One of a number of structures on the site linked to radar

development. Currently used for storage in association with

the school at Bawdsey Manor.



# RADAR TRANSMITTER BLOCK, BAWDSEY MANOR BAWDSEY

Grid Reference TM 341 383

List Grade II\* Conservation Area No

Description Concrete and brick radar block, 1937. Site of pioneering

radar development.

Suggested Use Radar museum

Risk Priority C Condition Fair

Reason for Risk Metal reinforcement is rusting causing concrete to spall.

Vegetation growth and drainage are also issues.

First on Register 2000

Owner/Agent Mr B Toettcher, Bawdsey Manor, Bawdsey, Woodbridge

**IP12 3AZ** 

Current Availability Not known

**Notes** 

One of the best preserved and least altered of the Chain Home transmitter blocks, a key structure in the original operation of radar. The Bawdsey Radar Trust is preparing a £1.5M lottery bid to conserve the building as a museum of radar. On English Heritage Register of Buildings at Risk.



# BATTERY OBSERVATION POST, EAST LANE BAWDSEY

Grid Reference TM 357 401

List Grade II Conservation Area No

Description A 2-storey reinforced concrete observation post, built in

1940 as the operational focal point of the local Emergency Coastal Defence Battery. An integral part of an exceptionally

complete World War Two coastal defence system.

Suggested Use Conversion to holiday let unit

Risk Priority D Condition Poor

Reason for Risk The in situ concrete walls are badly affected by spalling /

reinforcement corrosion.

First on Register 2006

Owner/Agent P J Mann, High House, Bawdsey, Woodbridge IP12 3AW

Current Availability For sale

Notes Planning permission was granted in April 2003 for change of

use to holiday unit.



## PRIORY FARMHOUSE CHEDISTON

Grid Reference TM 340 793

List Grade II Conservation Area No

Description C17 timber-framed and rendered farmhouse with later

alterations and extensions. A single long range in two sections. Two storeys with attic in eastern part. Plaintiled

roofs.

Suggested Use Residential

Risk Priority C Condition Poor

Reason for Risk Front wall bowing at west end, held up by brick buttress.

First on Register 1992

Owner/Agent Mr J D Ingate, Priory Farm, Halesworth Road, Chediston,

Halesworth IP19 0BB

Current Availability Not for sale

Notes Property is understood to be watertight following minor

repairs to roof completed in 2011.



1997 photograph

# MARTELLO TOWER 'T', FERRY ROAD FELIXSTOWE

Grid Reference TM 327 367

List Grade II and Scheduled Ancient Monument

Conservation Area No

Description Martello Tower on Felixstowe Ferry golf course. Built

c.1810-12 as part of defences against Napoleonic invasion. Brick with ashlar dressings, cement rendered. Felixstowe

originally had eight such towers.

Suggested Use Possible interpretation facility

Risk Priority C Condition Poor

Reason for Risk No solution agreed for future conservation and use.

First on Register 2014

Owner/Agent Felixstowe Ferry Golf Club, Ferry Road, Felixstowe IP11

9RY

Current Availability Not for sale

Notes English Heritage is in discussion with the owners over

repairs and interpretation.



### POST MILL, MILL ROAD **FRISTON**

TL 411 602 Grid Reference

List Grade ||\* **Conservation Area** No

Description Large early C19 post mill in centre of village. 3 storey

> weatherboarded buck on 3 storey painted brick roundhouse. Last worked by engine power in 1966. Now disused but

machinery largely intact.

Suggested Use Preserve as mill.

Risk Priority Α Condition Poor

Reason for Risk Repairs required to trestle. Damage to structural timbers

from deathwatch beetle. Lack of strategy to secure future

restoration and maintenance.

First on Register 2003

Owner/Agent Friston Mill Foundation, c/o Mr P Hartley, 8 Modbury

Gardens, Primrose Hill, London NW5 3QE

**Current Availability** Not for sale

Notes

In 2004 a steel frame was erected allowing the buck to be

supported independently off the weakened trestle. Some weatherproofing work and timber treatment carried out 2009-12. On English Heritage Register of Buildings at Risk.

Robert Scrimgeour 01394 444616



## THE ORANGERY, GLEVERING HALL, EASTON ROAD HACHESTON

Grid Reference TM 298 576

List Grade II\* Conservation Area No

Description Mid C19 Orangery in classical style with portico and

pilasters in stone between glazed panels. The roof has a shallow glazed dome. A particularly fine example of an

Orangery, designed by Decimus Burton.

Suggested Use Contact local authority

Risk Priority A

Condition Very bad

Reason for Risk Some glass missing, especially from the dome. Several

window frames are breaking up. Rusting iron cramps are

forcing off the stone facing.

First on Register 1992

Owner/Agent Mr Oliver Hurlock, Glevering Hall, Easton Road, Hacheston,

Woodbridge IP13 0EU

Current Availability Not for sale

Notes

English Heritage has grant-aided a condition survey and

conservation statement. On English Heritage Register of

Buildings at Risk.



### MAUSOLEUM 25M NORTH OF CHURCH OF ALL SAINTS, THE STREET HACHESTON

Grid Reference TM 312 585

List Grade II Conservation Area No

Description Early C19 mausoleum to Arcedeckne family, builders of

Glevering Hall. A symmetrical white brick building with simple classical detailing. Roof of stone flags. Surrounding

stone paving, formerly with perimeter railings.

Suggested Use Mausoleum

Risk Priority C Condition Poor

Reason for Risk Damage to brickwork and roof, mainly caused by vegetation.

Missing rainwater goods.

First on Register 2009
Owner/Agent Not known
Current Availability Not applicable

Notes Spot listed in 2007 in 'at risk' condition.
Contact Robert Scrimgeour 01394 444616



## CURLEW GREEN FARMHOUSE, CURLEW GREEN KELSALE CUM CARLTON

Grid Reference TM 381 653

List Grade II Conservation Area No

Description C16 timber-framed farmhouse in course of reconstruction

with some re-used queen-post roof trusses. Part of the red

brick south gable end is in situ.

Suggested Use Residential

Risk Priority F Condition Poor

Reason for Risk Under repair from ruinous condition; roof on and partly tiled

at time of survey.

First on Register 1992

Owner/Agent Mr P Dixon, 8 Crewys Road, London S15 2BH

Current Availability Not for sale

Notes Consent for rebuilding granted in 1994. Recently good

progress has been made and the timber frame, infill and roof structure are in place, and the roof partly tiled. The house

was derelict when listed in 1983.



# ORFORDNESS LIGHTHOUSE ORFORD

Grid Reference TM 449 489

List Grade II Conservation Area No

Description Lighthouse, built in 1792, of rendered brick, surmounted by

a lantern with lattice glazing and surrounding platform with

iron railings. Much of the original interior survives.

Suggested Use Lighthouse

Risk Priority E Condition Good

Reason for Risk Coastal erosion

First on Register 2012

Owner/Agent Orfordness Lighthouse Co. Ltd., Avocets, Quay Street,

Orford, Woodbridge IP12 2NU.

Current Availability Recently sold

Notes Decommissioned by Trinity House June 2013. Consent

granted August 2013 for removal of some fixtures.

Contact Robert Scrimgeour 01394 444616



Photo: Mike Page

# BRIDGE COTTAGES, THE CAUSEWAY PEASENHALL

Grid Reference TM 357 694

List Grade II Conservation Area Yes

Description Pair of late C17 or early C18 timber-framed and plastered

cottages under a pantiled roof.

Suggested Use Residential

Risk Priority C Condition Poor

Reason for Risk Prolonged lack of maintenance. Some roof tiles missing,

guttering broken. Frontage very overgrown.

First on Register 2000

Owner/Agent Exors of the late Mr J E Levett-Scrivener (contact Charles

Levett-Scrivener: <a href="mailto:levettscrivener@btinternet.co.uk">levettscrivener@btinternet.co.uk</a>)

Current Availability

Notes

Contact Robert Scrimgeour 01394 444616

Not known



# HILL FARMHOUSE, BADINGHAM ROAD PEASENHALL

Grid Reference TM 339 689

List Grade II Conservation Area No

Description Early C17 timber-framed and rendered farmhouse, within a

small group of farm buildings. Two storeys with attic. Plaintiled roof. Many window casements are later. Part of

the ground floor rebuilt in exposed breeze block.

Suggested Use Residential

Risk Priority C

Condition Very bad

Reason for Risk Render and lathes missing in several places. Large holes in

some walls, exposing internal frame.

First on Register 1992

Owner/Agent Exors of the late Mr J E Levett-Scrivener (contact Charles

Levett-Scrivener: <a href="mailto:levettscrivener@btinternet.co.uk">levettscrivener@btinternet.co.uk</a>)

Current Availability Not known.

Notes Internal chimney stack dismantled without consent c.2010.



## ELM ROW RAMSHOLT

Grid Reference TM 323 408

List Grade II Conservation Area No

Description Terrace of four red brick cottages. Early C19 with small later

C19 rear wings. Elm Row is an unusual survival, a littlealtered early C19 terrace of farm workers cottages.

Suggested Use Residential

Risk Priority C Condition Fair

Reason for Risk Vacant with decaying windows and general ingress of

water/damp. Much of the frontage is overgrown.

First on Register 2009

Owner/Agent The Trustees of the Adene Bawdsey Settlement, c/o Strutt

and Parker, 11 Museum Street, Ipswich IP1 3LN

Current Availability Not for sale

Notes In vulnerable condition when first listed on 6.1.2004.



## WINGFIELD HOUSE, MARKET PLACE SAXMUNDHAM

Grid Reference TM 386 632

List Grade II Conservation Area Yes

Description C17 timber-framed and rendered house, extended and

partly brick fronted in C19. Two storeys with attic. Pantiled and plaintiled roofs. Divided into three units. Forge building

in grounds.

Suggested Use Residential Condition Very bad

Risk Priority A

Reason for Risk Roof tiles and render missing. Major decay to the timber

frame.

First on Register 1992

Owner/Agent Mr E Upton, Wingfield House, Market Place , Saxmundham

**IP17 1AG** 

Current Availability Not for sale

Notes Some roof works were carried out in 2004/5, but there has

been little progress since. Suffolk Architectural Heritage Trust completed a Feasibility Study on the repair of the building in 2011-12 but the project was not pursued.



## REMAINS OF SIBTON ABBEY, YOXFORD ROAD SIBTON

Grid Reference TM 359 698

List Grade II; Scheduled Ancient Monument

Conservation Area No

Description Ruins of C12 Cistercian Abbey. Flint rubble with stone

dressings.

Suggested Use Conserve as ruin.

Risk Priority C Condition Poor

Reason for Risk Damaging vegetation. Occasional trespass and vandalism.

First on Register 2000

Owner/Agent Exors of the late Mr J E Levett-Scrivener (contact Charles

Levett-Scrivener: <a href="mailto:levettscrivener@btinternet.co.uk">levettscrivener@btinternet.co.uk</a>)

Current Availability Not known

Notes Site cleared of trees and other vegetation in March 2013. On

English Heritage Register of Buildings at Risk.



English Heritage photo c.2008

# ABBEY FARMHOUSE, YOXFORD ROAD SIBTON

Grid Reference TM 364 695

List Grade II Conservation Area No

Description C16 & early C17 timber-framed and plastered farmhouse

with plaintiled roof. Rear wing has shaped brick gable with oval windows. Red brick east wing probably added 1842.

Suggested Use Residential

Risk Priority C Condition Poor

Reason for Risk Prolonged lack of maintenance leading to numerous failings.

First on Register 2012 (Previously on the 1992 and 1995 Registers)

Owner/Agent Exors of the late Mr J E Levett-Scrivener (contact Charles

Levett-Scrivener: levettscrivener@btinternet.co.uk)

Current Availability Not for sale

Notes Located on working farm.



# GATEWAY 10M SOUTH OF THE LODGE, LONDON ROAD **THORINGTON**

Grid Reference TM 426 728

List Grade II Conservation Area No

Description Early C19 entrance gateway to the former Thorington Hall.

Four square cast iron piers, designed to imitate rusticated stonework; their cast iron urn finials are missing. Heavy cast

iron railings and gateposts supported by ornate iron

consoles.

Suggested Use Gateway

Risk Priority C Condition Poor

Reason for Risk Lack of maintenance coupled with damage from vehicle

impacts and vandalism.

First on Register 2003

Owner/Agent Dr F H Arustu, Thorington Hall, Thorington, Saxmundham

IP17 3QZ

Current Availability Not for sale

Notes The owner is looking to carry out repair work and is currently

seeking costs and securing funding.



## WINDPUMP ON WESTWOOD MARSHES WALBERSWICK

Grid Reference TM 486 736

List Grade II Conservation Area No

Description Red brick tower of former windpump, burnt out in 1960,

standing in National Nature Reserve. Some machinery

survives.

Suggested Use Conserve in low-key use.

Risk Priority C

Condition Very bad

Reason for Risk Disused and redundant. Open to elements after fire

damage.

First on Register 1995

Owner/Agent Sir Charles Blois, Estate Office, Poplar Farm, Hinton,

Darsham, Saxmundham IP17 3RJ

Current Availability Not for sale

Notes The mill stands in Natural England's Walberswick National

Nature Reserve. A scheme for conversion to an observation

point is under design.



# PACKWAY FARMHOUSE WALPOLE

Grid Reference TM 372 724

List Grade II Conservation Area No

Description Early C18 service range of a now demolished farmhouse.

Timber framed with a sheet metal roof. Shaped red brick

gable end to south.

Suggested Use Residential / agricultural storage

Risk Priority C Condition Poor

Reason for Risk In need of basic maintenance and repair to walls. Parts of

the building are overgrown.

First on Register 1992

Owner/Agent Mr M W Porter, Hill House Farm, Walpole, Halesworth IP19

9BQ

Current Availability Not for sale

Notes Isolated within a working farm. Repairs were carried out to

the shaped parapet brick gable end and chimney stack in

2011.



## THE GEORGE INN, HIGH STREET WICKHAM MARKET

Grid Reference TM 302 559

List Grade II Conservation Area Yes

Description List description dates the George Inn as early C18. Its

origins, however, are late medieval with (former) crown-post roof, wattle and daub infill panels and arched doorheads.

Suggested Use Public House / Hotel

Risk Priority A

Condition Very Bad Reason for Risk Fire damage

First on Register 2014

Owner/Agent

Current Availability Recently sold

Notes Fire occurred in April 2013 causing loss of roof and central

section of first floor and some damage to frame. Debris has been cleared, recorded and stored, where significant. The building is repairable and detailed proposals are awaited.



## 33 NEW MARKET BECCLES

Grid Reference TM 642 290

List Grade II Conservation Area Yes

Description Early C17 house with ground floor shop. Brick with some

timber framing, pantiled roof.

Suggested Use Mixed retail / residential

Risk Priority B

Condition Very Bad

Reason for Risk A recent fire has destroyed much of the roof structure, and

the building is inadequately weather protected.

First on Register 2015

Owner/Agent Douglas Gray c/o Neal Lewis, Lewis & Tyrrell Architects,

10 Stepping Lane, Norwich NR1 1PE

Current Availability Not for sale

Notes Building now weatherproof. New owner Spring 2017.

Applications received May 2017 for repairs to structure and

change of use of upper floors to create 3-bedroom flat.

Contact pbc@eastsuffolk.gov.uk



## FORMER ABATTOIR, REAR OF 26 BRIDGE STREET BUNGAY

Grid Reference TM 337 898

List Grade Curtilage building to 26 Bridge Street (Grade II)

Conservation Area Yes

Description L-shaped brick outbuilding of mainly C19 date, last used as

an abattoir. One of a group of outbuildings in the rear yard of

listed house/shop.

Suggested Use Heritage Centre or community use.

Risk Priority C

Condition Very Bad

Reason for Risk Requires significant structural repairs.

First on Register 1997

Owner/Agent Mr A R Buck, 26 Bridge Street, Bungay NR35 1HD

Current Availability Not for sale

Notes Negotiations to date have not secured any repairs.



### FARM BUILDINGS AT DUKES FARM, ST JOHN'S HILL BUNGAY

Grid Reference TM 347 886

List Grade Curtilage buildings to Barn at Duke's Farm (Grade II)

**Conservation Area** No

Description Two C17-C18 farm buildings. Timber-framed, clad in

weatherboards with some plasterwork, all under hipped

corrugated sheet steel roofs.

Suggested Use Commercial uses (light industry / storage)

Risk Priority Condition Poor

Reason for Risk Redundant buildings in need of structural repairs.

First on Register 2012

Owner/Agent Mr T Basey-Fisher, St Johns Hall Storage, St Johns Hall,

Ilketshall St John, Bungay IP35 8JQ

**Current Availability** Not for sale

**Notes** The main barn (listed Grade II) was largely destroyed by fire

> in April 2009. Consents granted for a live-work unit on the site of this barn, retaining and repairing remaining historic buildings for light industry / storage use. Work nearing

completion Spring 2017.

Contact pbc@eastsuffolk.gov.uk



## WARREN HOUSE COVEHITHE

Grid Reference TM 519 805

List Grade II Conservation Area No

Description House. C17. Timber framed, roughcast render, thatched

roof. In 2 sections of differing height. Main part 2 storeys and attic, 2 cell form with central axial stack; western section

single storey and attic.

Suggested Use Residential

Risk Priority B Condition Poor

Reason for Risk East gable render has failed and been removed. Gable

frame now covered by failing membrane.

First on Register 2017

Owner/Agent Benacre Estate, Benacre Estate Office, Hall Farm, Benacre,

Beccles, Suffolk NR34 7LJ (01502 675029)

Current Availability Not for sale Notes Tenanted

Contact pbc@eastsuffolk.gov.uk



## BRICK KILNS & CHIMNEY STACKS, FORMER GISLEHAM BRICK & PIPE WORKS GISLEHAM

Grid Reference TM 523 883

List Grade II Conservation Area No

Description Three downdraught pipe kilns and their two chimney stacks,

thought to date from the late 1940's. English bond brick walls and header bond brick domes without mortar, the drum

walls and their necks held together by steel bands.

Suggested Use Conserve as local historic manufacturing site.

Risk Priority C

Condition Very Bad

Reason for Risk Disused and redundant with lack of maintenance. The kilns

are especially liable to damage from rainwater and frost.

First on Register 2003

Owner/Agent E E Green & Son, 12 Church Road, Gorleston, Gt Yarmouth

**NR31 6NT** 

**Current Availability** 

**Notes** 

A lease may be available to secure their preservation.

The kilns stand within or adjacent to an aggregate recycling & waste recovery site. In 2016-7 the vegetation growing on and around the listed structures was cleared, and fencing is

to be erected to keep vehicles further away.

Contact pbc@eastsuffolk.gov.uk



# BARN AT SHADOWBARN FARM **ST MARGARET**, **ILKETSHALL**

Grid Reference TM 336 863

List Grade II Conservation Area No

Description Late C17 timber-framed and weatherboarded barn with

pantiled roof. C19 ranges adjoining. Remote, set in copse

surrounded by farmland.

Suggested Use Agricultural

Risk Priority C Condition Poor

Reason for Risk Disused and redundant.

First on Register 2003

Owner/Agent Mr D Skinner, Elms Farm, Ilketshall St Margaret, Bungay

**NR34 1QY** 

Current Availability Not for sale

Notes Decay of adjoining ranges hastens the overall decline.



## CROWN STREET HALL, CROWN STREET WEST LOWESTOFT

Grid Reference TM 549 939

List Grade II Conservation Area Yes

Description Former Fisher theatre built 1810, enlarged in 1850's with a

2-storey block fronting Crown Street. Rendered and

colourwashed brick with quoins, string course and parapet.

Pantiled roof.

Suggested Use Community centre

Risk Priority D Condition Poor

Reason for Risk Unusable in part and deteriorating through lack of

maintenance. Internal plasterwork has suffered from a

leaking parapet gutter.

First on Register 2006

Owner/Agent Wayne Sharp (contact details awaited)

Current Availability Not for sale

Notes Consents granted January 2016 for conversion to four

residential units. New owner expected to commence works

2017.



## STABLES & WALL AT WALMER HOUSE, LONDON ROAD, PAKEFIELD LOWESTOFT

Grid Reference TM 537 908

List Grade II Conservation Area Yes

Description Small early C19 coach house and stable constructed against

boundary wall. Elevations of flint and red brick with pantiled

roof.

Suggested Use Residential

Risk Priority D Condition Poor

Reason for Risk General lack of maintenance with structural cracking and

spalling brickwork.

First on Register 2006

Contact

Owner/Agent Mr Peter Adams, Walmer House, London Road, Pakefield,

Lowestoft NR33 0PB

Current Availability Not for sale

Notes Planning permission and listed building consent for

conversion to holiday accommodation granted September 2012. The approved works have begun with a new build garage; conversion of the coach house is to follow.

pbs@eastsuffolk.gov.uk



## MOAT FARMHOUSE SHADINGFIELD

Grid Reference TM 428 851

List Grade II\* Conservation Area No

Description C16 farmhouse with C19 alterations and brick wing to rear.

Good quality timber frame with longwall jetty. Finely moulded beams and joists internally. Early example of

unstaggered butt purlin roof. Moated site.

Suggested Use Residential

Risk Priority C

Condition Very Bad

Reason for Risk External envelope largely clad in temporary sheeting, with

decayed plasterwork elsewhere. Major repairs required but

little progress for many years.

First on Register 1992

Owner/Agent Miss R Neale and Mr D Ramm, Moat Farmhouse,

Shadingfield, Beccles NR34 8DL

Current Availability Not for sale

Notes In

In early 1980's the interior was extensively altered and partly

dismantled following the collapse of the chimney stack. On

Historic England Register of Heritage at Risk.

Contact pbc@eastsuffolk.gov.uk



## GOLDINGS FARM BARNS, SMITHS ROAD **SOTTERLEY**

Grid Reference TM 647 285

List Grade Curtilage buildings to Goldings Farmhouse (Grade II)

Conservation Area No

Description Main barn C18. Brick with sheet metal roof. Range of lower

brick outbuildings with pantiled roofs.

Suggested Use Domestic use has been approved

Risk Priority F

Condition Fair-Poor

Reason for Risk Long term lack of maintenance. Now requires structural

repairs.

First on Register 2015

Owner/Agent Justin Henry, Norfolk Barns Ltd. (07823777747)
Current Availability For sale once development has been completed.
Notes Residential conversion under way Spring 2017.

Contact pbc@eastsuffolk.gov.uk



## WHALEYS, ST JAMES ROAD SOUTH ELMHAM ALL SAINTS & ST NICHOLAS

Grid Reference TM 633 282

List Grade II\* Conservation Area No

Description Former farmhouse. Mid to late C16. 2 storeys and attics;

3-cell plan, with internal chimney stack and cross-entry. Timber-framed and rendered, with thatched roof. Finely

moulded beams and pargetting internally.

Suggested Use Residential

Risk Priority C Condition Poor

Reason for Risk Lack of maintenance and repair over many years.

First on Register 2015

Owner/Agent Winky Evans, Whaleys, St James Road, South Elmham All

Saints, Halesworth IP19 0HG

Current Availability Not for sale

Notes Full structural survey carried out Autumn 2016 and efforts

are being made to address its findings.



# WHITE HOUSE FARMHOUSE SOUTH ELMHAM ALL SAINTS & ST NICHOLAS

Grid Reference TM 322 828

List Grade II Conservation Area No

Description C17 farmhouse of 2-cell plan form with end chimney stack.

Timber-framed, partly rendered, partly clad in painted brick.

Pantiled roof. C19 and C20 casement windows.

Suggested Use Residential

Risk Priority C Condition Poor

Reason for Risk Failing plasterwork and external joinery, partly overgrown.

First on Register 2012

Owner/Agent Mr J Walpole, White House Farm, St Nicholas South

Elmham, Harleston IP20 0PS

Current Availability Not for sale

Notes Some work under way December 2015 including lime render

repairs and replacement timber capping to bargeboards.



## BARN TO SW OF VALLEY FARMHOUSE WANGFORD WITH HENHAM

Grid Reference TM 433 781

List Grade II Conservation Area No

Description Early C19 timber-framed and weatherboarded barn, with

corrugated iron roof. In 5 bays.

Suggested Use Residential

Risk Priority D Condition Poor

Reason for Risk Redundant structure. Areas of missing weatherboarding.

First on Register 2006

Owner/Agent Hektor Rous, The Henham Estate, The Office, Henham

Park, Henham, Beccles NR34 8AN

Current Availability Not for sale

Notes Consent for residential conversion granted August 2000.

Groundworks were carried out in 2005, constituting

commencement of development. Revised scheme granted

consent February 2011.



## SERVICE RANGE TO VALLEY FARMHOUSE WANGFORD WITH HENHAM

Grid Reference TM 434 781

List Grade II Conservation Area No

Description Mid C16 timber-framed building, altered and extended in

C17 and later to form service range to farmhouse. Timber framed and plastered to the north, the remainder largely

rebuilt in late C18 red brick. Black pantiled roof.

Suggested Use Ancillary / residential

Risk Priority D Condition Poor

Reason for Risk Redundant structure. Brick addition to east now roofless and

north side overgrown. Both roof slopes have missing tiles.

First on Register 2006

Owner/Agent Hektor Rous, The Henham Estate, The Office, Henham

Park, Henham, Beccles NR34 8AN

Current Availability Not for sale

Notes Consent for residential conversion granted August 2000.

Groundworks were carried out in 2005, constituting

commencement of development. Revised scheme granted

consent February 2011.

Contact pbc@eastsuffolk.gov.uk



# BARN TO WEST OF BLEACH FARMHOUSE WISSETT

Grid Reference TM 373 796

List Grade II Conservation Area No

Description Timber framed barn, roof clad with corrugated aluminium

sheeting. Inscription inside records the erection of the barn

in 1772.

Suggested Use Storage

Risk Priority C Condition Poor

Reason for Risk Redundant from agriculture. Wattle and daub wall areas

exposed and in decay.

First on Register 2000

Owner/Agent Mrs J Ash (01502 218836)

Current Availability Not for sale

Notes



## NORTHERNMOST BARN AT PARK FARM, LOCKS LANE WRENTHAM

Grid Reference TM 650 283

List Grade II Conservation Area No

Description Barn. Late C17. Timber framed, weatherboarded, thatched

roof.

Suggested Use Agricultural use

Risk Priority B Condition Poor

Reason for Risk Long term lack of maintenance. Now requires structural

repairs.

First on Register 2015

Owner/Agent Benacre Estate, Benacre Estate Office, Hall Farm, Benacre,

Beccles, Suffolk NR34 7LJ (01502 675029)

Current Availability Not for sale

Notes Still in use for agricultural storage

Contact pbc@eastsuffolk.gov.uk

